

# ANNOUNCEMENT



Ministry of Economy

## Service Campaign for Front Passenger's Airbag Inflator

**HONDA**  
The Power of Dreams

In co-ordination between the Ministry of Economy - Department of Consumer Protection, and in line with the keenness of the Ministry of Economy to conduct an ongoing review of all the products in the UAE and provide the consumer with the required protection, Al-Futtaim Honda announces a service campaign for MY 2003 – 2004 CR-V, MY 2003 – 2004 Stream, MY 2003 – 2004 Civic, and MY 2004 Jazz.

In certain vehicles, the passenger side airbag inflator may rupture during deployment due to abnormal pressure, and push metal fragments through the airbag.

The decision has been taken jointly with Honda Motor Co. Ltd. and the Ministry of Economy - Department of Consumer Protection to launch a service campaign to carry out the inspection of those 1,696 vehicles affected in the UAE and, if required, replace with the modified part to ensure that we give our customers peace of mind.

Al-Futtaim Honda requests all customers who own these vehicles with the VIN falling in the range listed below, to call the Customer Care Centre on **800-HONDA** or log on to our website [www.honda.ae](http://www.honda.ae) and make a booking with an Al-Futtaim Honda Service Centre.

Model	Model Type	Model Year	VIN Range	
			From	To
CR-V	RD5	2003	3C400961	3C401381
CR-V	RD5	2004	4C400001	4C401028
Stream	RN3	2003	3C400371	3C400374
Stream	RM3	2004	4C400001	4C400065
Civic	ES1	2003	3S400946	3S401202
Civic	ES1	2004	4S400003	4S400650
Civic	ES8	2004	4S400170	4S405656
Jazz	GD1	2004	4S400004	4S400307

The Vehicle Identification Number (VIN) or the chassis number appears on the plate attached to the driver's doorjamb and on a plate fastened to the top of the dashboard on the driver's side.