

ANNOUNCEMENT



Ministry of Economy

Service Campaign for Driver Airbag Inflator (U.A.E.)

HONDA
The Power of Dreams

In co-ordination between the Ministry of Economy - Department of Consumer Protection, and in line with the keenness of the Ministry of Economy to conduct an ongoing review of all the products in the UAE and provide the consumer with the required protection, Al-Futtaim Honda announces a service campaign for 2007 CR-V; 05 – 06 City; 06 – 07 Civic; 05 – 07 Jazz.

In certain vehicles, there is a possibility of abnormal output from the Driver's airbag inflator container which may lead to abnormal airbag deployment.

The decision has been taken jointly with Honda Motor Co. Ltd. and the Ministry

of Economy - Department of Consumer Protection to launch a service campaign to carry out the inspection of those vehicles affected in the UAE and replace with modified part to ensure that we give our Customers peace of mind. The replacement will start from the 15th of June 2015.

Al-Futtaim Honda requests all Customers who own these vehicles with the VIN falling in the range listed below to call the Customer care centre on **800-HONDA** OR log on to our website www.honda.ae and make a booking with any Al-Futtaim Honda Service Centre.

Model	Model Type	Model Year	VIN Range	Affected Vehicle Nos.
CR-V	RE4	2007	7C400003 - 7C404601	514
City	GD6	2005	5P020421 - 5P030686	609
City	GD6	2006	6P060379 - 6P060439	2
Civic	FD1	2006	6S400031 - 6S414995	6,452
Civic	FD1	2007	7S400001 - 7S403054	1,536
Jazz	GD1	2005	5S400026 - 5S400575	354
Jazz	GD3	2006	6S400010 - 6S400695	507
Jazz	GD3	2007	7S400001 - 7S400237	170

The Vehicle Identification Number (VIN) or the chassis number appears on the plate attached to the driver's doorjamb and on a plate fastened to the top of the dashboard on the driver's side.